

Exa[®] PACS/RIS

Feature Summary: Customize the Viewer Toolbar

© 2020 Konica Minolta Healthcare Americas, Inc.



You can change the button size, thumbnail location, and sensitivity of tools of the viewer toolbar by following the procedure below.

See also, "Configure the toolbar" in the user's manual.

1. On the settings imenu, select **Viewer Settings**.

STAT 0 1 0 0 1 0	TAT 0	000 🥳	<u>ን</u> ወ
PENDING FINAL APPROVAL	<	>00@1	7 Q
RIPTION 🖨	DOB	MODALITY	STUDY
		All 🔻	All
ening - Combo	08/13/1965	MG	BAM/

2. On the **INTERFACE SETTINGS** tab, make changes and then click **SAVE**.

Viewer Options					
GENERAL INFO	Toolbar				
INTERFACE Toolbar Button Scale SETTINGS		100 %			
	Magnify Glass Size	400 px.Factor 2			
MODALITY OPTIONS	W/L Acceleration	200			
MAMMOGRAPHY OPTIONS	Span Sensitivity	2 ?			
	Thumbnail Column/Rows	1 *			
OVERLAY	Thumbnail Bar Orientation	Bottom *			
TOOLS	Header Menu	Тор *			
EXTERNAL TOOLS	DM Toolbar	Top *			
	Caliper Position				
	🗌 Left 🗌 Top 🗹 Right 🗹	Bottom			